

## Tina Lee

---

**From:** Richard Hicks  
**Sent:** Thursday, November 4, 2021 9:35 AM  
**To:** Tina Lee  
**Subject:** Please upload  
  
**Importance:** High

Tina upload this to all these tickets , also 14163

Work Order	Description	Location / Fac. ID	Amount	CSS #
14997	OLD WO#14681 -AC in Server Room not working correctly	DE002-01	3819.43	31842
13889	JG Have sport bottle water fountains installed	DE007-01	5379.42	29290
14523	There are about 75 emergency lights not working-150 BATTERIES NEEDED	DE007-01	8030	30954
14545	Wall pack exhaust fan- asset 1057 Switch is broken and not getting power to the switch.	DE007-01	3185.56	31520
13950	CH : Repair to slope of tile floor in male latrine, 1st floor bldg 002, to allow for proper drainage	MD002-01	17344.37	25532
14385	AC is down in building 1 Main Lobby	MD002-01	38038.69	30986
15353	Issues with CAC access system-troubleshoot entire system diagnose and repair	MD002-01	3040	32964
12917	[KAugustin]Ensure proper communication between all components and BAC; create schedules for zones of	MD002-02	6222.2	25758
12856	BLDG 0003 MEP lights (2) not working-Power supply severed	MD002-03	7817.25	26133
12582	BLDG 314 -MEP and POV lights are not working	MD002-04	11192.02	26132
15134	Repair to carpet tiles in common area. Several tiles are frayed and coming off the floor, trip hazard	MD013-01	13465.82	32912
12765	Proposal to upgrade to LED bulbs for wall pack lights on main building , pump house , OMS	MD019-01	8254	PENDING
13852	JG There are numerous lights out in the building. The reason is not known at this time. There are 12	MD019-01	5717.12	29281
14163	West side fence line is less than required height, barbed wire strands are also loose and compressed	MD021-01	26625.72	30423
15015	FCU-Asset# 2105#49 Fan Motor drive line needs replaced and unit checked for proper operation	MD021-01	2735.14	32388
14365	Outdoor condenser has a bad leak . Completely flat with oil stained coils. It controls 4 indoor unit	MD024-01	14001.33	30816
15117	Repair bldg 1003 breakroom interior swing door with sealed door type, pre hung.	MD024-01	4680.52	32797
13168	1-Replace Vestibule light bulbs with LED 2-Replace (14) Foyer lights with LED 3- Replace (5) air f	MD066-01	5030.21	27576

---

**From:** Richard Hicks

**Sent:** Thursday, November 4, 2021 8:53 AM

**To:** Gabrielle Mascelli <gabrielle.mascelli@tideh2o.net>; Adam Colopy <adam.colopy@tideh2o.net>

**Cc:** Tina Lee <Tina.Lee@cmimgmt.com>

**Subject:** Please update your trackers

**Importance:** High

Gabby ,

These tickets were canceled by Ken , Please pay incurred costs to S&S and inform Lindsay these were canceled -----these are billing out in October OY4

Work Order	Description	Site	Location / Fac. ID	Site Code	CLIN	CSS #
12765	Proposal to upgrade tp LED bulbs for wall pack lights on main building , pump house , OMS	99REG5	MD019-01	24491	4002-AI	PENDIN
13889	JG Have sport bottle water fountains installed	99REG5	DE007-01	10801	4002-AC	29290
13950	CH : Repair to slope of tile floor in male latrine, 1st floor bldg 002, to allow for proper drainage-- <b>pay incurred costs</b>	99REG5	MD002-01	24725	4002-AD	25532
14385	AC is down in building 1 Main Lobby -- <b>Please tell Lindsay and pay \$450</b>	99REG5	MD002-01	24725	4002-AD	30986
14997	OLD WO#14681 -AC in Server Room not working correctly- <b>Pay incurred costs</b>	99REG5	DE002-01	10735	4002-AB	31842

Thanks,  
Rick

Rick Hicks  
Project Manager Region 5  
CMI Management Inc.  
5285 Shawnee Road Suite #510  
Alexandria,VA 22312  
703-738-5301  
[Richard.Hicks@cmimgmt.com](mailto:Richard.Hicks@cmimgmt.com)