

Date: 4/11/2025



Region: 4A

FEMS No.: 3071277

FAC ID: NY010

Maximo WO No.: 18287

Asset #: NA

Priority: Routine

**Original Work Request:**

Repair interior wall. Common area room 144 has a large crack in the drywall going from the ceiling to the floor. Wall to the right side of crack does not feel stable and moves when pushed. Needs to be reinforced and repaired with drywall.

**Description of Repairs Needed:**

Labor and material to a) Repair large crack in sheetrock wall. Reinforce wall where available. Fill crack, finish and paint repair area. Multiple coats required. Will allow one coat to dry, will return another day to perform additional coat. (Multiple trips to complete)

Labor:	Labor Hrs	Labor Rate	Total
Service Technician	16	\$ 100.00	\$ 1,600.00
			\$ -

Material List:	Quantity	Cost	Total
Material (mesh, compound, lumber, paint)	1	\$ 120.00	\$ 120.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA
----

**Estimate Summary:**

Labor	Material	Equipment
\$ 1,600.00	\$ 120.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,720.00	\$206.40	\$103.20	\$2,029.60

**HUNOLD CONTRACTING INC.**

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: Julie Pape

6625 Selmick Dr., Suite A

Elkridge, MD 21075

**ESTIMATE****3/28/25**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	FEMS 30771277, NY010 Amherst, NY WO18287  Repair large crack in sheetrock wall. Reinforce wall where available. Fill crack, finish and paint repair area. Multiple coats required.  Material: \$120 (mesh, compound, lumber, paint) Labor: (16 hours @ \$100/ hr.) =\$1600	<b>1720.00</b>
<b>Sub total</b>		<b>1720.00</b>
<b>Sales Tax</b>		<b>N/A</b>
<b>Total</b>		<b>1720.00</b>

**Signature**\_\_\_\_\_ **Date**\_\_\_\_\_**Signature**\_\_\_\_\_ **Date**\_\_\_\_\_

