

Date: 4/10/2025

Region: 4C

FEMS No.: 3113932

FAC ID: WV046

Maximo WO No.: 18510

Asset #:

NA

Priority:

Emergency



**Original Work Request:**

Repair rainwater leaking into the Drill Hall around windows. Windows also need to be flashed with new flashing and the brick is cracked and needs to be repointed.

**Description of Repairs Needed:**

Labor and material to a) repair to brick, b) reflash, c) mortor point on Drill Hall windows.

**Labor:**

	Labor Hrs	Labor Rate	Total
Labor (4 techs x 2 days)	64	\$ 115.63	\$ 7,400.00
		\$	-

**Material List:**

	Quantity	Cost	Total
Materials (flashing, mortor)	1	\$ 3,000.00	\$ 3,000.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 7,400.00	\$ 3,000.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$10,400.00	\$1,248.00	\$624.00	\$12,272.00



## Gribble Roofing Co.

1512 Gihon rd

mike@gribbleroofing.com

ESTIMATE

EST0299

DATE

04/07/2025

TOTAL

USD \$10,400.00

TO

### TIDEWATER, INC

□ 9044651981

■ 14105791685

Julie.pape@tideh2o.net

DESCRIPTION	RATE	QTY	AMOUNT
REPAIR TO BRICK, REFLASH AND MORTOR POINT ON DRILL HALL WINDOWS.SITE ADDRESS PFC USARC/BMA 102 CAMDEN AVE, PARKERSBURG WV 26101 Labor estimated at 7400 material cost estimated to be \$3000. Flashing, mortar,	\$10,400.00	1	\$10,400.00
TOTAL			USD \$10,400.00

\$7200 DEPOSIT

\$7200 DUE UPON COMPLETION

Contractor carries \$2 million Insurance wage bond and 15 year craftsmanship warranty

