

Date: 5/5/2025

Region: 4A

FEMS No.: 3113989

FAC ID: NY126

Maximo WO No.: 18522

Asset #: NA

Priority: Routine



Original Work Request:

Repair light fixtures. Note all bulbs listed are T-5 type. Need 10 18-inch fluorescent bulb for men's restroom and locker area. Need 10 48-inch fluorescent bulb for kitchen. Need 10 48-inch fluorescent bulb for hallways. Ballast may need replacement if changing bulbs doesn't repair light fixtures.

Description of Repairs Needed:

Labor and material to a) repair interior lights as needed, b) supply & install (20) T5 4' bulbs, c) supply & install (10) T5 18" bulbs, d) supply & install (5) T5 2 bulb ballasts, e) test for proper operation, f) clean up and properly dispose of all spent materials at job site.

Labor:	Labor Hrs	Labor Rate	Total
Technician	12	\$ 100.00	\$ 1,200.00
			\$ -

Material List:	Quantity	Cost	Total
T5 4' Bulbs	20	\$ 4.00	\$ 80.00
T5 18" Bulbs	10	\$ 7.70	\$ 77.00
T5 2 Bulb ballast	5	\$ 21.00	\$ 105.00
			\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,200.00	\$ 262.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,462.00	\$175.44	\$87.72	\$1,725.16

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
5/1/25

Quantity	Description	Amount
1	FEMS 3113989, WO 18522, NY126 Chili, NY Repair interior lights as needed. Materials per SOW. Material: (\$262) 20-T5 4' bulbs. (\$80) 10-T5 18" bulbs. (\$77) 5- T5 2 bulb ballasts. (\$105) Labor: (12 hours @ \$100/ hr.) = \$1200	1462.00
		Sub total 1462.00
		Sales Tax N/A
		Total 1462.00

Signature _____ Date _____

Signature _____ Date _____