

Date: 5/16/2025

Region: 4A

FEMS No.: 3156257

FAC ID: NY070

Maximo WO No.: 18790

Asset #: NA

Priority: Routine



Original Work Request:

Repair overhead door in VMS building. Make repair to top right roller on overhead door. The roller sometimes jump the track when its in use. The door is the north west door on the VMS building.

Description of Repairs Needed:

Labor and material to repair overhead door by replacing the overhead door assembly, making adjustments as needed, test for proper operation. Clean up area and properly dispose of all spent materials at job site.

Labor:

	Labor Hrs	Labor Rate	Total
Service Technician	7	\$ 100.00	\$ 700.00
			\$ -

Material List:

	Quantity	Cost	Total
Commercial Roller Assembly	1	\$ 83.00	\$ 83.00
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 700.00	\$ 83.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$783.00	\$93.96	\$46.98	\$923.94

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
5/16/25

Quantity	Description	Amount
1	FEMS 3156257, WO 18790, NY070 Webster, NY Repair overhead door NW bay of AMSA shop. Material: (\$83 commercial roller assembly.) Labor: (7 hours @\$100/ hr.) = \$700	783.00
	Sub total	783.00
	Sales Tax	N/A
	Total	783.00

Signature _____ Date _____

Signature _____ Date _____