

Date: 5/19/2025

Region: 4A

FEMS No.: 3156552

FAC ID: NY010

Maximo WO No.: 18847

Asset #: NA

Priority: Routine



Original Work Request:

During building walkthrough, a basketball sized dent was noted in drywall located in room 172 (drill hall). Wall will need to be patched and repainted, hole is directly where 2 paint colors meet.

Description of Repairs Needed:

Labor and material to repair damaged sheetrock on drill hall wall. Fill crack, finish and paint repair area. Multiple coats required. Clean area and properly dispose of debris from site.

Labor:	Labor Hrs	Labor Rate	Total
Labor	12	\$ 100.00	\$ 1,200.00
			\$ -

Material List:	Quantity	Cost	Total
Mesh, compound, lumber, paint	1	\$ 80.00	\$ 80.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,200.00	\$ 80.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,280.00	\$153.60	\$76.80	\$1,510.40

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: Julie Pape
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
3/28/25

Quantity	Description	Amount
1	FEMS 3156552, WO18847, NY010 Amherst, NY Repair damaged sheetrock on drill hall wall. Fill crack, finish and paint repair area. Multiple coats required. Material: \$80 (mesh, compound, lumber, paint) Labor: (12 hours @ \$100/ hr.) = \$1200	1280.00
		Sub total 1280.00
		Sales Tax N/A
		Total 1280.00

Signature _____ Date _____

Signature _____ Date _____