

Date: 5/16/2025

Region: 4A

FEMS No.: 3156597

FAC ID: NY052

Maximo WO No.: 18856

Asset #: NA

Priority: Routine



Original Work Request:

Replace Men's shower head needs to have the shower head replaced and a new soap dish installed in the shower stall. Repair roof exhaust cover. Most likely needs new hardware. Replace damaged mailbox to include post and mailbox.

Description of Repairs Needed:

Labor and material to a) repair roof top vent, b) supply and install men's shower head, c) supply and install large mailbox with address on new treated post, d) supply and install new soap dish in the shower stall, e) clean area and properly dispose of all spent materials at job site.

Labor:

	Labor Hrs	Labor Rate	Total
Service Technician	12	\$ 100.00	\$ 1,200.00
			\$ -

Material List:

	Quantity	Cost	Total
Large Arlington mailbox, treated post, shower head, letters & hardware	1	\$ 154.00	\$ 154.00
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,200.00	\$ 154.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,354.00	\$162.48	\$81.24	\$1,597.72

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
5/15/25

Quantity	Description	Amount
1	FEMS 3156597, WO 18856, NY052 Penn Yan, NY Repair roof top vent. Repair men's shower head. Replace mailbox and post. Replace soap dish. Material: (\$154 -large Arlington mailbox, treated post, shower head, letters and hardware) Labor: (12 hours @ \$100/ hr.) = \$1200	1354.00
		Sub total 1354.00
		Sales Tax N/A
		Total 1354.00

Signature _____ Date _____

Signature _____ Date _____