

Date: 9/26/2025

Region: 4C

FEMS No.: 3220135

FAC ID: WV009

Maximo WO No.: 20090

Asset #: NA

Priority: Urgent



Original Work Request:

Repair parts washer - seals have deteriorated and water just gushes out.

Description of Repairs Needed:

Labor and material to a.) take apart parts washer and replace seal kit, b.) clean up and properly dispose of all spent materials.

Labor:

	Labor Hrs	Labor Rate	Total
Technicians	8	\$ 90.00	\$ 720.00
		\$	-

Material List:

	Quantity	Cost	Total
Seal Kit	1	\$ 79.56	\$ 79.56
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 720.00	\$ 79.56	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$799.56	\$95.95	\$47.97	\$943.48



DBA TC3 Services
142 Terrace Manor
Fairmont, WV 26554

Estimate

Date	Estimate #
9/26/2025	1126

Name / Address
Tidewater Inc Julie Pape 6625 Selnick Drive, Ste A Elkridge, MD 21075

Description	Hours	Rate	Total
Clarksburg: Parts Washer FEMS 3220135 WO 20090 Seals have deteriorated and water gushes out.			
Take apart parts washer and replace seal kit.			
Materials: Seal Kit: Equipment Manufacturing Labor:	8	79.56 90.00	79.56 720.00
Thank you for doing business with Tri-City Electric!			
Approval Signature:			Total \$799.56
tcemelissa@gmail.com	Phone: 304-363-2843		