

Date: 10/2/2025

Region: 4C

FAC ID: WV010

Asset #: NA

FEMS No.: 3313769

Maximo WO No.: ~~20087~~ 20330

Priority: Urgent



**Original Work Request:**

Repair VAV 10 & exhaust fans. Repair VAV 10 - leaking through ceiling tile and making noise and also to repair exhaust fans in both men and women's restrooms in training building.

**Description of Repairs Needed:**

Labor and material to a.) Repair exhaust ventilation system for latrines, b.) Repair door in OMS office, c.) Repair VAV #10, d.) clean up and properly dispose of spent materials.

Labor:	Labor Hrs	Labor Rate	Total
Technicians	18	\$ 135.00	\$ 2,430.00
Labor assessment 6 hrs @\$135 = \$810.00 - \$198 = \$612.00	1	\$ 612.00	\$ 612.00

Material List:	Quantity	Cost	Total
Belt for Exhaust System	1	\$ 48.32	\$ 48.32
Balancig valve	1	\$ 298.66	\$ 298.66
Ball Valve Parker	1	\$ 150.64	\$ 150.64
Insulation	1	\$ 109.60	\$ 109.60
Misc. copper pipe and press fit connections	1	\$ 423.33	\$ 423.33
Consumables	1	\$ 100.00	\$ 100.00
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA
----

**Estimate Summary:**

Labor	Material	Equipment
\$ 3,042.00	\$ 1,130.55	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,172.55	\$500.71	\$250.35	\$4,923.61

**CUSTOM CONSTRUCTION**  
**CHRIS MOORE**  
**103 SWEITZER RD.**  
**ACME PA.15610**  
**(724) 244-9438**

**PROPOSAL FEMS # 3313769**

**DATE: 10/1/25**

**SUBMIT TO:**

JULIE PAPE  
TIDEWATER

**LOCATION**

BRIDGEPORT USARC WV010  
BRIDGEPORT, WV.

**WORK TO BE PERFORMED**

REPAIR EXHAUST VENTILATION SYSTEM FOR LATRINES  
REPAIR DOOR IN OMS OFFICE  
REPAIR VAV #10

MATERIAL BELT FOR EXHAUST SYSTEM \$ 48.32  
BALANCING VALVE \$298.66  
BALL VALVE PARKER \$150.64  
INSULATION \$109.60  
MISC. COPPER PIPE AND PRESS FIT CONNECTIONS \$423.33  
CONSUMABLES \$100.00

LABOR 18 HRS. @ \$135.00/HR. = \$2,430.00

LABOR INCURRED 6 HRS. @ \$135.00/HR. = \$810.00

**ESTIMATE \$ 4,370.55**