

Additional Funding Request

Site: WV046	WO# 7591 CSS # 17516 Asset# NA
Description of Repairs	Investment is labor and materials to repair a glycol leak on the hot water supply pipe for AHU-3 at USARC Parkersburg, WV046, CSS #14558.
Diagnosis: Initial Work Order CSS# 17516	The rear bay door farthest from office in BMA 102 will not open. Circuit breakers were checked and none were tripped. Please diagnose and restore to usable condition.
Explanation of Additional Costs for Repairs	Investment is labor and materials to make repairs to electrical shorts, add relay and check door operation
Additional Labor Cost to Perform Repairs	\$1,308.96
Additional Material Cost to Perform Repairs	\$214.47 + 423.47 (Incurred)
Total Cost of Repair	\$1,946.90

(To be completed by the Contractor and saved in the Contractor's CMMS)

Contractor Personnel on Site:

Work Performed: evaluation with for repair

[illegible]

To be signed by the Contractor:

Signed: 

I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Signed: [Signature]

E-Mail: Dwayne.a.felton4.civ@mail.mil

