



Level of glycol in automatic feeder used for hotwater loop is very low. Request is for vendor to add necessary amount of glycol to holding tank and confirm feeder is working correctly

Proposal to provide and perform the following:

- Provide and install 35% Ethylene Glycol with inhibitors with yellow/greenish color 35 gallons
- Start up
- Warranty