



Multiple physical security related issues with the supply cages were discovered during most recent physical security inspection. Issues include unsecured framing on caging doors and disconnected panels on the ceiling of the cages. Currently ceiling is being supported by ratchet straps. Next inspection is scheduled for June.

WORK TO BE PERFORMED

MAKE NECESSARY REPAIRS TO SECURITY CAGING IN MULTIPLE AREAS

INSTALL NEW SECURITY PANELS

CLEAN UP AND DISPOSE OF DEBRIS PROPERLY

CMI Cost Estimate								
Funding Request								
PA096 Washington								
Multiple physical security related issues								
CSS #17176 - CMI # 7534								
Prepared By: J. Bayne								
2/11/2019								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 80.00	16						\$ 1,280.00
1.2 Material					\$ -	\$ -	\$ -	\$ 281.85
20% Mark up								\$ 56.20
1.3 Consumables								\$100.00
Sub Total Repair Cost								\$ 1,718.05
2. Initial Service Call Investigation								
Grand Total								\$ 1,718.05