



Exhaust fans located in both the men's and women's latrines have become inoperable. Breakers have not been tripped. Request is for vendor to troubleshoot and repair.

Proposal to provide and perform the following:

- Properly remove defective Motor, Belt, Sheave
- Provide and install (1) Motor, Browning Belt, Sheave
- Start up
- Warranty

CMI Cost Estimate								
Funding Request								
PA096 Washington								
Exhaust fans located in both the men's and women's								
CSS #17181 - CMI # 7542								
Prepared By: J. Bayne								
02.07.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	4						\$ 392.00
1.2 Motor, Browning Belt, Sheave					\$ -	\$ -	\$ -	\$ 228.74
1.3 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 644.74
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	1.5						\$ 147.00
Grand Total								\$ 791.74