

## Additional Funding Request

PA051	CSS # 15808	WO5921	ASSET #
Description of Repairs	Furnish labor and material to install a new gate valve in the pump house at the Flight facility.		
Diagnosis: Initial Work Order	Domestic water pump house. Backflow preventer cannot be tested due to leaking 6" gate valve upstream of device. Quote is to replace gate valve and do backflow test. Water Authority is requesting this be completed ASAP.		
Explanation of Additional Costs for Repairs	\$130.00 Backflow test		
Additional Labor Cost to Perform Repairs	\$ 480.00		
Additional Material Cost to Perform Repairs	\$ 1320.00		
Shipping	N/A		
Total Cost of Repair	\$ 1930.00		