



Repair ductless units: Rm 111 - Condensate pump not working; Rms 101, 115, 116 - units not heating - fan speed not working in heat mode;

Proposal to provide and perform the following:

- Replace the faulty condensate pump for room 111
- Rooms 101, 115 & 116 – Will work once the board is replaced as part of CSS 14801.

CMI Cost Estimate								
Funding Request								
PA080 Punxsutawney								
Repair ductless units: Rm 111								
CSS #16446 - CMI # 8121								
Prepared By: J. Bayne								
3.04.19								
P3 Routine								
Asset 5215								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 80.00	2.75						\$ 220.00
1.2 Condensate Pump					\$ -	\$ -	\$ -	\$ 194.23
Sub Total Repair Cost								\$ 414.23
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 80.00	2						\$ 160.00
Grand Total								\$ 574.23