

## Additional Funding Request

<b>PA027</b>	<b>CSS# 16164 WO# 7567 Asset# 3152</b>			
Description of Repairs	Labor and materials to replace, and install condenser fan motor, blade, and capacitor, on AAON RTU			
Diagnosis: Initial Work Order	The roof top AHU is not working. We had the Spyder control for the HVAC controls replaced for this unit, but have found that the fuses keep popping when the unit is turned on and the unit will still not operate. There is no heat on the second floor. Urgent request.			
Diagnostic Fee	\$0			
Additional Labor Cost to Perform Repairs	\$ 780.00  Renick Brothers Labor \$120.00/hr x 6 Travel Time Round trip \$1.00/mile x 60			
Additional Material Cost to Perform Repairs	\$ 572.00			
	Condenser fan motor # R1746B	1	\$440.00	\$440.00
	Capacitor # P5130B	1	7.00	\$7.00
	Fan Blade, # P86780 CDS	1	\$125.00	\$125.00
Total Cost of Repair	\$ 1,352.00			



1075  
0  
5.4  
E INS  
SEMI-ENCL.  
NORMALLY PROTECTED  
TH 15.0 MFD 370 VAC  
CA 15.0  
ASSEMBLED IN MEXICO  
**P85460**

VOLTS 208-230  
TYPE UF  
1  
AMB 40°C  
AIR OVER DUTY

SP®

BROWN  
WHITE  
BLACK

LINE

614129 614131-004





## Additional Funding Request

<b>PA027</b>	<b>CSS# 16164 WO# 7567 Asset# 3152</b>			
Description of Repairs	Labor and materials to replace, and install condenser fan motor, blade, and capacitor, on AAON RTU			
Diagnosis: Initial Work Order	The roof top AHU is not working. We had the Spyder control for the HVAC controls replaced for this unit, but have found that the fuses keep popping when the unit is turned on and the unit will still not operate. There is no heat on the second floor. Urgent request.			
Diagnostic Fee	\$0			
Additional Labor Cost to Perform Repairs	\$ 780.00  Renick Brothers Labor \$120.00/hr x 6 Travel Time Round trip \$1.00/mile x 60			
Additional Material Cost to Perform Repairs	\$ 572.00			
	Condenser fan motor # R1746B	1	\$440.00	\$440.00
	Capacitor # P5130B	1	7.00	\$7.00
	Fan Blade, # P86780 CDS	1	\$125.00	\$125.00
Total Cost of Repair	\$ 1,352.00			