

Additional Funding Request

NY126	CSS# 16697 WO# 6843 Asset# 7787
Description of Repairs	<p>Labor and Equipment to troubleshoot overhead door. Lift is required to diagnose.</p> <p>Note: This lift will be used to also investigate and/or complete CSS 17072.</p>
Diagnosis: Initial Work Order	Troubleshoot and repair overhead door in OMS. The door has been having issues closing. Repair is needed before the door stops working completely.
Diagnostic Costs	\$ 0
Additional Labor Cost to Perform Repairs	<p>\$ 640</p> <p>Labor (1) Technician \$80/Hr x 8</p>
Additional Material Cost to Perform Repairs	\$ 0
Additional Equipment Cost to Perform Repairs	<p>\$ 446.25</p> <p>Sunbelt Lift rental.</p>
Total Cost of Repair	\$ 1086.25

