

Additional Funding Request

MD003	CSS# 25791 WO# 12465 Asset# NA															
Description of Repairs	SS was on site and able to repair the unit in rm 109 by cleaning all piping and trimmed a piece of pipe to allow water to drain. Diagnosed unit in rm 125 it needs new condensate discharge hose. Will replace discharge hose and complete system ck to insure everything is working properly.															
Diagnosis: Initial Work Order	There are two thermostats that are not getting power, this is causing the each A/C unit to not work. The first is Zone 1st on the first floor closest to the main entry and the 2nd is at the end of the classroom wing, closest to the rear doors.															
Diagnostic Fee	\$ 500															
Additional Labor Cost to Perform Repairs	<p>\$ 900</p> <p>Labor \$100/hr x 9</p>															
Additional Cost	<p>\$ 297.26</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Clear tubing 50 ft</td> <td>2</td> <td>\$15.40</td> <td>\$250.80</td> </tr> <tr> <td>Worm Clamps</td> <td>1</td> <td>\$11.46</td> <td>11.46</td> </tr> <tr> <td>Shipping</td> <td></td> <td></td> <td>35.00</td> </tr> </table>				Clear tubing 50 ft	2	\$15.40	\$250.80	Worm Clamps	1	\$11.46	11.46	Shipping			35.00
Clear tubing 50 ft	2	\$15.40	\$250.80													
Worm Clamps	1	\$11.46	11.46													
Shipping			35.00													
Total Cost of Repair	\$ 1,697.26															



CUSTOMER QUOTATION NO. 330

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 12465
Quote No: 330
Site: MD003 Liberty Heights
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 07/28/2020
Valid For: 30 Day(s)

WO 12465

CSS 25791

Problem: "There are two thermostats that are not getting power, this is causing the each A/C unit to not work. The first is Zone 1st on the first floor closest to the main entry and the 2nd is at the end of the classroom wing, closest to the rear doors."

S&S was onsite and was able to repair the unit in room 109 by cleaning all piping, and trimmed a piece of pipe to allow water to drain.

S&S diagnosed the unit in room 125 needs a new condensate discharge hose.

S&S will remove and replace the discharge hose and then complete a system check to ensure everything is working properly.

Service

Item	Quantity	Unit Price	Total
Clear Tubing 50 ft	2.00	\$125.40	\$250.80
Worm Clamps	1.00	\$11.46	\$11.46
Shipping	1.00	\$35.00	\$35.00
Diagnosis Fee	1	\$500.00	\$500.00
HVAC Labor Rate	9	\$100.00	\$900.00
Sub-Total ex Tax			\$1,697.26
Tax			\$0.00
Total inc Tax			\$1,697.26

Labor	\$1,400.00
Materials	\$297.26
Sub-Total ex Tax	\$1,697.26
Tax	\$0.00
Total inc Tax	\$1,697.26

My Products



TYGON

50 ft. Tygon Tubing with 3/8" Inside
Dia., Clear

Item # 9MH86

Price \$104.50 / each



GRAINGER APPROVED

1/2" Wide, Interlocked Worm Gear
Hose Clamp; PK10

Item # 5CZF2

Price \$9.55 / pkg. of 10

PHONE

1-800-472-4643

HOURS

M-F 7:30 AM - 3:00 PM Eastern

[Show Reference Information](#) | [Clear](#)

Qty

[Update](#)
[Remove](#)

TOTAL

\$104.50

Qty

[Update](#)
[Remove](#)

TOTAL

\$9.55

Products You Have Recently Viewed

