

Additional Funding Request

Submitted: 07/26/21

MD066 – Heat pump alarms	CSS # 31694 WO# 14669											
Description of Repairs	S&S proposes to remove and replace (3) outdoor wall back lights near the elevator.											
Original SC Investigative Diagnosis	\$300.00											
Diagnosis: Initial Work Order	Three Wall Pack Lights are not working on the outdoor walls near the Elevator											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$707.54 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts (See detail in quote)</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$707.54</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts (See detail in quote)	1	1	\$707.54
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Parts (See detail in quote)	1	1	\$707.54									
Additional Labor Cost to Perform Repairs	Labor: \$1000.00 10 hours each/Rate \$100.00 per hour = \$1000.00											
Total Cost of Repair	\$2,007.54											