

Additional Funding Request

Submitted: 10/15/2021

MD013- MEP Light Asset 3Y262	CSS #32419 WO#15124								
Description of Repairs	S&S proposes to remove and replace the ballast & photocell on MEP light asset# 3Y262. S&S will then check to ensure the light is working properly.								
Original SC Investigative Diagnosis	NA								
Diagnosis: Initial Work Order	MEP LIGHT NOT WORKING Asset # 3Y262, located in grassed fence area								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$1,164.21</p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>Parts and Lift(see detail attachments)</td><td>1</td><td></td><td>1,164.21</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts and Lift(see detail attachments)	1		1,164.21
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Parts and Lift(see detail attachments)	1		1,164.21						
Additional Labor Cost to Perform Repairs	<p>Labor: \$1000.00 10 hours each/Electrical Rate \$100.00 per hour = \$1,000.00</p>								
Total Cost of Repair	\$2,164.21								