

## Additional Funding Request

Submitted: 9/1/2020

<b>MD013 – fuses</b>	<b>CSS #26470 WO# 12764</b>																			
Description of Repairs	Upstairs is too hot, 82 degrees all upstairs. Check VAV boxes in duct work to see if cool air is moving upstairs.																			
Original SC Investigative Diagnosis	<b>\$500.00</b>																			
Diagnosis: Initial Work Order	S&S was onsite and found that fuses are needed for machine to run properly																			
Explanation of Additional Costs for Repairs	N/A																			
Additional Material Cost to Perform Repairs	<b>Materials Total: \$204.52</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;"><b>ITEM</b></th><th style="text-align: left; padding: 2px;"><b>QUANTITY</b></th><th style="text-align: left; padding: 2px;"><b>UNIT PRICE</b></th><th style="text-align: left; padding: 2px;"><b>TOTAL</b></th></tr> </thead> <tbody> <tr> <td style="padding: 2px;">See attached detail for materials cost</td><td style="padding: 2px;"></td><td style="padding: 2px;"></td><td style="padding: 2px;">\$191.34</td></tr> <tr> <td style="padding: 2px;"> </td><td style="padding: 2px;"></td><td style="padding: 2px;"></td><td style="padding: 2px;"> </td></tr> <tr> <td style="padding: 2px;">Shipping</td><td style="padding: 2px;">1</td><td style="padding: 2px;">\$13.18</td><td style="padding: 2px;">\$13.18</td></tr> </tbody> </table>				<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	See attached detail for materials cost			\$191.34					Shipping	1	\$13.18	\$13.18
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>																	
See attached detail for materials cost			\$191.34																	
Shipping	1	\$13.18	\$13.18																	
Additional Labor Cost to Perform Repairs	<b>Labor: \$300.00</b> HVAC Labor Tech/3 hours/Rate \$100.00 per hour = \$300.00																			
<b>Total Cost of Repair</b>	<b>\$1,004.52</b>																			