

Additional Funding Request

Submitted: 5.19.20

MD013 – pressure switch	CSS #25177 WO #12316
Description of Repairs	Chiller Circuit #1 - oil pressure switch needs replaced and need time to investigate
Diagnosis: Initial Work Order	While onsite performing PMs, S&S diagnosed Circuit #1 needs a new oil pressure switch. After removing and installing the new oil pressure switch, we will then complete a system check to ensure everything is running properly.
Diagnostic Fee	Diagnostic Total: NA
Explanation of Additional Costs for Repairs	NA
Additional Labor Cost to Perform Repairs	Labor: \$900.00 HVAC Labor Rate /9 hours/ Rate \$100.00 per hour = \$900.00
Additional Material Cost to Perform Repairs	Materials: \$620.64 Carrier Oil Pressure Switch/HK06UC001 / \$526.65 Tax: \$43.99 Shipping: \$50.00
Total Cost of Repair	\$1,520.64