

Region: 5

Location: MD016

CSS # 349

Maximo Work Order No.: 17341

Asset #: NA

Date Issued: 05/10/22

Original Description: Repair 2nd Hanging heater vent pipe, elbow has a hole in the bottom inside the OMS building work bay, Also check the vent cap and replace as needed

Repairs Needed:

S&S will remove and replace the damaged duct, fittings and install a new flu cap.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Parts detailed in attached Quote	--	--	\$322.41	--	\$322.41
--	NA	Shipping	--	--	\$200.00	--	\$200.00
		19 ft Scissor Lift			\$667.16		\$667.00
--	NA	Diagnostic	4	\$80.00			\$320.00
--	NA	Labor	25	\$80.00	--	--	\$2,000.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Lift	Total Cost	CE Factor	Total Estimate
29	\$2,320.00	\$522.41	\$667.16	\$3,509.57	106%	\$3,720.14