

Region: 5

Location: MD016

CSS # 361

Maximo Work Order No.: 17343

Asset #: NA

Date Issued: 05/10/22

Original Description: Repair Grease Trap doors, Missing one lead. From the flagpole facing the building, on right side near sidewalk.

Repairs Needed:

S&S proposes to remove and replace the shattered front entry glass.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	PARTS DETAIL IN ATTACHED QUOTE	--	--	\$1,713.99	--	\$1,713.99
--	NA	Shipping	--	--	\$200.00	--	\$200.00
--	NA	Diagnostic	5	\$80.00			\$400.00
--	NA	Labor	20	\$80.00	--	--	\$1,600.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
25	\$2,000.00	\$1,913.99	NA	\$3,913.99	100%	\$3,913.99