

### Additional Funding Request

Submitted: 4/5/2019

<b>MD016 – sump pump installation</b>	<b>CSS #18544 WO #8449</b>			
Description of Repairs	<p>Installed new sump pump into existing pit in motor room.          Inspected all equipment to ensure in working order.          Removed switch gear panels and electrical controlled devices.          Utilized electrical drying agent to dry all electrical components.          Cleaned area up from water intrusion.          Additional parts needed.          Will submit quote on separate work order.</p>			
Diagnosis: Initial Work Order	<p>4/3/19 will return for follow up, we have KO approval.</p> <p>4/3/19- Patrick replaced air filters in AHU that got wet. Installed 20x25x2 new filters and got AHU ready to run. Worked with S&amp;S Mechanical.</p>			
Diagnostic Fee	<p><b>Diagnostic Total: \$344.17</b></p> <p>CMI On-site Support Labor (Patrick) - \$80/hr x 4 = \$320.00          Graingers filter cost = \$24.17          (\$344.17 See attached CMI invoice)</p>			
Explanation of Additional Costs for Repairs	NA			
Additional Labor Cost to Perform Repairs	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	HVAC Labor Rate	13.00 hrs	\$100.00	\$1,300.00
	<b>Total Labor</b>			<b>\$1,300.00</b>
Additional Material Cost to Perform Repairs	<b>Materials: \$267.96</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	Electric contact cleaner	1.00	\$60.91	\$60.91
	Sump Pump	1.00	\$205.61	\$205.61
	Adapter	1.00	\$1.44	\$1.44
	<b>Total - Excluding Tax</b>			<b>\$267.96</b>
<b>Total Cost of Repair</b>	<b>\$1,912.13</b>			