

Additional Funding Request

MD019 – Roof	Maximo WO # 6009 CSS# 14889 Asset #NA
Description of Repairs	Labor and materials to reseal and secure end of roof where it is uplifting.
Diagnosis: Initial Work Order	Found a water damaged ceiling tile in room 219. Removed damaged tile and found a number of previous tiles pushed to the sides. Pulled all of them down. At the time, I could see no evidence of water leaking from pipes or roof. Left tiles out and asked Mr. Parrish to keep an eye on the area if it rained. During next site visit it was raining and there is a roof leak in the area above. Leak needs to be patched to prevent further damage and ceiling tiles replaced with new ones.
Explanation of Additional Costs for Repairs	Labor and material to repair the roof.
Investigative Diagnosis from SC	\$0 Subcontractor did not charge a diagnostic fee
Additional Material Cost to Perform Repairs	\$540.00
Additional Labor Cost to Perform Repairs	\$0
Total Cost of Repair	\$540.00

Karlee Demain

From: Sam Abramson <sam@parkheightsroofing.com>
Sent: Thursday, November 1, 2018 4:53 PM
To: Karlee Demain
Cc: Adam Colopy
Subject: Re: New Requests - CSS 15664 WO 6002 CSS 14889 WO 6009 MD024 & MD019

Karlee,

Please review recommended work for 12100 Greenspring Avenue:

Reseal and secure end of roof where uplifting for \$540.

Please let me know if you'd like to proceed.

Thank you,

Make it a Great Day!

Regards,


Sam Abramson

*Commercial Account Manager
Park Heights Roofing, Inc.*

Cell: 443-768-9031

Email: Sam@parkheightsroofing.com

Website: www.parkheightsroofing.com



On Thu, Nov 1, 2018 at 10:46 AM Karlee Demain <karlee.demain@tideh2o.net> wrote:

Sam,

No problem, I will let the base know.

How did the site visit go at MD019?