

**Additional Funding Request
Corrective Maintenance from PM**

Submitted: 11/13/2018

MD021 – Boiler #4, rear view port	CSS #16299 WO#6475 Asset# 2097
Description of Repairs	S&S hereby proposes to install view port for Boiler #4
Diagnosis: Initial Work Order	The rear view port is not installed properly and is allowing the products of combustion to discharge into the boiler room due to Argent's recommendation
Explanation of Additional Costs for Repairs	N/A
Investigative Diagnosis from SC	N/A
Additional Material Cost to Perform Repairs	<p><u>Materials:</u> = \$197.64</p> <p>Viewport Asy/ #W385600099 = \$164.42</p> <p>Tax = \$8.22</p> <p>Shipping: \$25.00</p>
Additional Labor Cost to Perform Repairs	<p><u>Labor:</u></p> <p>1 HVAC Technician /4hours/ Rate \$100.00 per hour = \$400.00</p>
Total of Corrective Maintenance Ticket	\$597.64
Minus \$250 – Cost of CM credit	(\$250.00)
Total Cost of Repair	\$347.64