

Additional Funding Request

Submitted: 01/20/21

MD021-Hobart Mixer Repair	CSS #28446 WO# 13464			
Description of Repairs	S&S proposes to remove and replace the timer knob/board on the Hobart mixer and will then complete a system check to make sure everything is running as intended.			
Original SC Investigative Diagnosis	\$100			
Diagnosis: Initial Work Order	Repair Mixer (HOBART) Electrical Issues			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials: \$709.08			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
	PCD Board Assembly/00-917212 and shipping	1	\$330.21	\$330.21
Additional Labor Cost to Perform Repairs	Labor: \$300 Plumber Labor Tech/3 hours/Rate \$100.00 per hour = \$300.00			
Total Cost of Repair	\$930.21			