

Additional Funding Request

Submitted: 06/15/2021

MD021- Grease Trap	CSS # 31033 WO# 14388											
Description of Repairs	B&P to schedule pumping of one external grease interceptor up to 450 gallons. Power wash inside grease trap (has grease build up).											
Original SC Investigative Diagnosis	NA											
Diagnosis: Initial Work Order	Power wash outdoor grease trap tank											
Explanation of Additional Costs for Repairs	\$870.00 B&P Service See Price Validation											
Additional Material Cost to Perform Repairs	Materials: NA <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: right; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"></td><td style="text-align: left; padding: 2px;"></td><td style="text-align: left; padding: 2px;"></td><td style="text-align: right; padding: 2px;">\$</td></tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL				\$
ITEM	QUANTITY	UNIT PRICE	TOTAL									
			\$									
Additional Labor Cost to Perform Repairs	Labor: \$400.00 4 hours each/Rate \$100.00 per hour = \$400.00											
Total Cost of Repair	\$1,270.00											