

Additional Funding Request

Submitted: 0708/2021

MD021-Card Reader	CSS # 31521 WO# 14547			
Description of Repairs	As per your request, LoCurrent Systems is pleased to provide a quotation to replace Drill Hall Door Reader with new			
Original SC Investigative Diagnosis	NA			
Diagnosis: Initial Work Order	Replace Drill Hall Door Reader-Bad Keypad			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials: \$1250.00			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
	Parts (See detail in quote)	1	1	\$1250.00
Additional Labor Cost to Perform Repairs	Labor: \$350.00 4 hours each/Rate \$75.00 per hour /Admin fee \$50.00= \$350.00			
Total Cost of Repair	\$1600.00			