

Additional Funding Request

Submitted: 09/20/21

MD021 -FCU rm 204	CSS # 32549 WO# 15026											
Description of Repairs	S&S proposes to remove and replace the actuator on the FCU in unit 204.											
Original SC Investigative Diagnosis	\$100.00											
Diagnosis: Initial Work Order	FCU in 204 is not working properly 80 degrees on 13 SEPT.											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$92.18 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th><th style="text-align: left; padding: 2px;">QUANTITY</th><th style="text-align: left; padding: 2px;">UNIT PRICE</th><th style="text-align: left; padding: 2px;">TOTAL</th></tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Actuator</td><td style="text-align: left; padding: 2px;">1</td><td style="text-align: left; padding: 2px;">92.18</td><td style="text-align: left; padding: 2px;">92.18</td></tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Actuator	1	92.18	92.18
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Actuator	1	92.18	92.18									
Additional Labor Cost to Perform Repairs	Labor: \$400.00 4 hours each/HVAC Rate \$100.00 per hour = \$400.00											
Total Cost of Repair	\$592.18											