

## Additional Funding Request

Submitted: **12/07/2021**

<b>MD021-Lighting/Ceiling Tiles</b>	<b>CSS #32988 WO#15366</b>			
Description of Repairs	S&S herby proposes to replace (13) 2 lamp ballasts, (26) T8 bulbs and 14 ceiling tiles in rooms 106,107,108,109,111,201,204 and above middle stairwell.			
Original SC Investigative Diagnosis	<b>\$150.00</b>			
Diagnosis: Initial Work Order	1 light above middle stairwell. 2 lights outside Rm 106. Rm107 6 tiles. Rm 108 8 lights 6 tiles. Rm 109 5 lights, 1 tile. Rm 111 2 lights, 1 tile. Rm 201 2 lights. Outside Rm 204 2 lights			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	<b>Materials: \$ 420.73</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	<b>(See Quote for Detail)Ceiling Tiles/Ballast/Bulbs</b>	<b>1</b>	<b>\$420.73</b>	<b>\$420.73</b>
Additional Labor Cost to Perform Repairs	<b>Labor: \$800.00</b> 8 hours each/Electrical Rate \$100.00 per hour = \$800.00			
<b>Total Cost of Repair</b>	<b>\$1,370.73</b>			