

## Additional Funding Request

Submitted: **12/22/0021**

<b>MD021-Asset #1554 Refrigerator</b>	<b>CSS #33184 WO#15385</b>								
Description of Repairs	S&S found the hot discharge gas line corroded and leaking refrigerant. S&S recommends rebuilding corroded line and charging system.								
Original SC Investigative Diagnosis	<b>\$300.00</b>								
Diagnosis: Initial Work Order	Investigate temp on Refrigerator Asset 1554 reading 99*								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p><b>Materials: \$ 283.54</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;"><b>ITEM</b></th> <th style="text-align: left; padding: 2px;"><b>QUANTITY</b></th> <th style="text-align: left; padding: 2px;"><b>UNIT PRICE</b></th> <th style="text-align: left; padding: 2px;"><b>TOTAL</b></th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"><b>Details in Quote</b></td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;"><b>\$283.54</b></td> <td style="text-align: left; padding: 2px;"><b>\$283.54</b></td> </tr> </tbody> </table>	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	<b>Details in Quote</b>	1	<b>\$283.54</b>	<b>\$283.54</b>
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>						
<b>Details in Quote</b>	1	<b>\$283.54</b>	<b>\$283.54</b>						
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$900.00</b> 10 hours each/HVAC Rate \$100.00 per hour = \$900.00</p>								
<b>Total Cost of Repair</b>	<b>\$1,483.54</b>								