

## Additional Funding Request

Submitted: 4/12/2022 Revised

<b>MD021 BAC System</b>	<b>CSS #34684 WO#16760</b>											
Description of Repairs	S&S found BAS is not reading temp correctly, S&S proposes to remove and replace the Trane return water temperature sensor. S&S will then complete a system check to ensure everything is working properly.											
Original SC Investigative Diagnosis	<b>\$1,100.00</b>											
Diagnosis: Initial Work Order	BAC is not working; all AHU are offline											
Explanation of Additional Costs for Repairs	S&S further found the Netgear ethernet switch not operating and recommend replacement											
Additional Material Cost to Perform Repairs	<p><b>Materials: \$ 104.63</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;"><b>ITEM</b></th> <th style="text-align: left; padding: 2px;"><b>QUANTITY</b></th> <th style="text-align: left; padding: 2px;"><b>UNIT PRICE</b></th> <th style="text-align: left; padding: 2px;"><b>TOTAL</b></th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts and shipping</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$104.63</td> <td style="text-align: left; padding: 2px;">\$104.63</td> </tr> </tbody> </table>				<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	Parts and shipping	1	\$104.63	\$104.63
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>									
Parts and shipping	1	\$104.63	\$104.63									
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$</b>            6 hours each/HVAC Rate \$100.00 per hour = \$600.00</p>											
<b>Total Cost of Repair</b>	<b>\$1804.63</b>											