

Additional Funding Request

Submitted: 4/12/2022

MD021 Thermostat	CSS #35061 WO#16920											
Description of Repairs	S&S replaced the Honeywell Thermostat but after further investigation found the ignition control is bad and needs replaced											
Original SC Investigative Diagnosis	\$600.00											
Diagnosis: Initial Work Order	OMS Bay Thermostat needs replacing, Broken knob. Location is in the first pole in the 1st work bay.											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	<p>Materials: \$ 415.63</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts see detail in quote</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$415.63</td> <td style="text-align: left; padding: 2px;">\$415.63</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts see detail in quote	1	\$415.63	\$415.63
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Parts see detail in quote	1	\$415.63	\$415.63									
Additional Labor Cost to Perform Repairs	<p>Labor: \$500.00 5 hours each/HVAC Rate \$100.00 per hour = \$500.00</p>											
Total Cost of Repair	\$1,515.63											