

Additional Funding Request

Submitted: 2/11/2019

MD021 – exhaust fan motor, 2 pillow bearings	CSS #16729 WO#7258
Description of Repairs	Rm 213B exhaust fan loud, heavy vibration; 218 -2 light fixtures, 2nd FL hall, 102 & 110
Diagnosis: Initial Work Order	S&S went out to investigate repairs for room 213B exhaust fan extremely loud with heavy vibration. Room 218 has 2 light fixtures, 2nd floor hallway light fixture, room 102 and room 110 light fixture: S&S will need to return to install an exhaust fan motor and 2 pillow bearings.
Explanation of Additional Costs for Repairs	N/A
Investigative Diagnosis from SC	\$414.28 Note that lights were replaced and were covered in the \$414 diagnostic fee
Additional Material Cost to Perform Repairs	Materials: \$290.48 Pillow bearings/3FDA4 qty 2 = \$65.30 Motor/6K965/qty 1 = \$187.53 Tax: \$12.65 Shipping: \$25.00
Additional Labor Cost to Perform Repairs	Labor: \$500.00 1 HVAC Technician/5hours/ Rate \$100.00 per hour = \$500.00
Total Cost of Repair	\$1,204.76