

## Additional Funding Request

Submitted: 11/19/2018

|   |  |
|---|--|
| <b>MD021 – fence gate</b>                   | <b>CSS #16147 WO#6431</b>  |
| Description of Repairs                      | Repair, align main gate after unknown vehicular impact damage.   |
| Diagnosis: Initial Work Order               | <p>S&amp;S furnished the labor and material necessary for the completion of the following:</p> <ul style="list-style-type: none"> <li>- S&amp;S Will furnish <math>\frac{1}{4}</math>" thick aluminum plating to secure to the broken fence gate.</li> <li>- S&amp;S will prime and paint black to match existing fencing, all hardware will be rust resistant.</li> <li>- Work will take place during normal business hours.</li> </ul> |
| Explanation of Additional Costs for Repairs | N/A  |
| Investigative Diagnosis from SC             | N/A  |
| Additional Material Cost to Perform Repairs | <p><b>Material= 391.38</b></p> <ul style="list-style-type: none"> <li>- <math>\frac{1}{4}</math>" thick aluminum plate/ Qty 2/ \$170.11 each</li> <li>- 1in screws/ \$10.51 total</li> <li>- Grey Etching Primer/ Qty 2 / \$5.71 each</li> <li>- Black Protective Enamel/ Qty 2/ \$4.82 each</li> <li>- Tax &amp; Shipping = \$19.59</li> </ul>  |
| Additional Labor Cost to Perform Repairs    | <p><b>Labor = \$375.00</b></p> <ul style="list-style-type: none"> <li>- 1 tech/ 5 hours/ \$75 an hour</li> </ul>   |
| <b>Total Cost of Repair</b>                 | <b>\$766.38</b>  |