

## Additional Funding Request

Submitted: 5/31/2019

<b>MD021</b> – roof vent over DFAC	<b>CSS #19429 WO# 9012</b>
Description of Repairs	Vent on top of roof over DFAC fan belt and motor needs repair, unit not working.
Original SC Investigative Diagnosis	<b>\$200.00</b>
Diagnosis: Initial Work Order	<p>S&amp;S proposes to furnish the labor and material necessary for the completion of the following:</p> <ul style="list-style-type: none"> <li>- S&amp;S will remove the old motor and replace with new motor and belt.</li> <li>- Work will take place during normal business hours.</li> </ul>
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<b>Material: \$245.92</b> Fan motor/2518OS1BSPAO48/ \$236.54 Belt/BAL200/\$9.38
Additional Labor Cost to Perform Repairs	<b>Labor: \$300.00</b> 1 Electrician /3 hours/ Rate \$100.00 per hour = \$300.00
<b>Total Cost of Repair</b>	<b>\$745.92</b>