

## Additional Funding Request

Submitted: 5/31/2019

<b>MD021</b> – roof vent over DFAC	<b>CSS #19431 WO# 9008</b>
Description of Repairs	Vent on top of roof over DFAC fan belt and motor needs repair, unit not working.
Original SC Investigative Diagnosis	<b>\$200.00</b>
Diagnosis: Initial Work Order	<p>S&amp;S proposes to furnish the labor and material necessary for the completion of the following:</p> <ul style="list-style-type: none"> <li>- S&amp;S will remove the old motor and replace with new motor and belt.</li> <li>- Work will take place during normal business hours.</li> </ul>
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<p><b>Materials = \$267.03</b>            Fan motor/CK48HB07J01/ \$258.05            Belt/BAX20/\$8.98</p>
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$300.00</b>            1 Electrician /3 hours/ Rate \$100.00 per hour = \$300.00</p>
<b>Total Cost of Repair</b>	<b>\$767.03</b>