

## Additional Funding Request

Submitted: 11/14/19

<b>MD021</b> – smell of gas on MAU unit	<b>CSS #22268 WO #11271</b>																										
Description of Repairs	Smell of gas when near unit. Unit tripping off some safety issue. Diagnosed a bad fan pressure switch, or flame controller, and or flame sensor.																										
Diagnosis: Initial Work Order	S & S proposes to remove and replace the following materials on the MAU Unit at MD021. S & S will then complete a system check to ensure everything is running correctly.																										
Diagnostic Fee	<b>Diagnostic Total: \$400.00</b>																										
Additional Labor Cost to Perform Repairs	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;"><b>ITEM</b></th><th style="text-align: left;"><b>QUANTITY</b></th><th style="text-align: left;"><b>UNIT PRICE</b></th><th style="text-align: left;"><b>TOTAL</b></th></tr> </thead> <tbody> <tr> <td>HVAC Labor Rate</td><td style="text-align: center;">6</td><td style="text-align: center;">\$100/hr</td><td style="text-align: center;">\$600.00</td></tr> <tr> <td><b>Total Labor</b></td><td></td><td></td><td style="text-align: center;"><b>\$600.00</b></td></tr> </tbody> </table>			<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	HVAC Labor Rate	6	\$100/hr	\$600.00	<b>Total Labor</b>			<b>\$600.00</b>												
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>																								
HVAC Labor Rate	6	\$100/hr	\$600.00																								
<b>Total Labor</b>			<b>\$600.00</b>																								
Additional Material Cost to Perform Repairs	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;"><b>ITEM</b></th><th style="text-align: left;"><b>QUANTITY</b></th><th style="text-align: left;"><b>UNIT PRICE</b></th><th style="text-align: left;"><b>TOTAL</b></th></tr> </thead> <tbody> <tr> <td>Contactor</td><td style="text-align: center;">1.00</td><td style="text-align: center;">\$484.49</td><td style="text-align: center;">\$484.49</td></tr> <tr> <td>Overload Relay</td><td style="text-align: center;">1.00</td><td style="text-align: center;">\$119.30</td><td style="text-align: center;">\$119.30</td></tr> <tr> <td>Shipping</td><td style="text-align: center;">1.00</td><td style="text-align: center;">\$150.00</td><td style="text-align: center;">\$150.00</td></tr> <tr> <td>Tax</td><td></td><td style="text-align: center;">\$00.00</td><td style="text-align: center;">\$00.00</td></tr> <tr> <td><b>Total Cost Materials</b></td><td></td><td></td><td style="text-align: center;"><b>\$753.79</b></td></tr> </tbody> </table>			<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	Contactor	1.00	\$484.49	\$484.49	Overload Relay	1.00	\$119.30	\$119.30	Shipping	1.00	\$150.00	\$150.00	Tax		\$00.00	\$00.00	<b>Total Cost Materials</b>			<b>\$753.79</b>
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>																								
Contactor	1.00	\$484.49	\$484.49																								
Overload Relay	1.00	\$119.30	\$119.30																								
Shipping	1.00	\$150.00	\$150.00																								
Tax		\$00.00	\$00.00																								
<b>Total Cost Materials</b>			<b>\$753.79</b>																								
<b>Total Cost of Repair</b>	<b>\$1,753.79</b>																										