

Additional Funding Request

Submitted: 10.28.2020

MD066 – #1686/WO#13129 Follow Up Quotation #1686 (WO#13129) to repair Telephone Intercom at the White Plains MD066 Facility.	CSS #27240 WO# 13129			
Description of Repairs	Repair Telephone Intercom at the White Plains MD066 Facility.			
Original SC Investigative Diagnosis	\$650.00			
Diagnosis: Initial Work Order	<p>As per original diagnostic LoCurrent arrived on site, found Units described as "AiPhones" to instead be non-functional Telephone-based Telephone Intercoms. Telephone Intercom Units were found to be non functional due to the fact there were no telephone lines connected.</p> <p>LoCurrent Systems will provide a Follow Up Quotation to test for dial-tone in TER Room and make cross connects that will need to end at the Rear Gate location and begin in Main Building 1st Floor TER Room. Dial-tone must then be verified at Telephone Intercom locations for complete operation at the White Plains, MD USARC MD066.</p>			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials:			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
Additional Labor Cost to Perform Repairs	Labor: \$650.00 2 Labor Tech/4 hours/Rate \$75.00 per hour = \$600.00 Administrative = \$50.00			
Total Cost of Repair	\$650.00			