

Additional Funding Request

Submitted: 5/28/2020

MD066 – Diakin Expansion Card replacement	CSS #25272 WO#12321																				
Description of Repairs	Main -AHU -Needs Diakin Expansion card replaced -it controls compressor starting																				
Original SC Investigative Diagnosis	NA																				
Diagnosis: Initial Work Order	S&S was onsite doing PM's and discovered the expansion board needs replaced. S&S proposes to install a new expansion board and check the operation to ensure everything is working properly.																				
Explanation of Additional Costs for Repairs	N/A																				
Additional Material Cost to Perform Repairs	<p>Materials: \$220.53</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">ITEM</th><th style="text-align: left;">QUANTITY</th><th style="text-align: left;">UNIT PRICE</th><th style="text-align: left;">TOTAL</th></tr> </thead> <tbody> <tr> <td>Expansion Board/ 212610</td><td>1</td><td>\$181.46</td><td>\$181.46</td></tr> <tr> <td>Tax</td><td></td><td>\$9.07</td><td>\$9.07</td></tr> <tr> <td>Shipping</td><td></td><td>\$30.00</td><td>\$30.00</td></tr> <tr> <td>TOTAL</td><td></td><td></td><td>\$220.53</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Expansion Board/ 212610	1	\$181.46	\$181.46	Tax		\$9.07	\$9.07	Shipping		\$30.00	\$30.00	TOTAL			\$220.53
ITEM	QUANTITY	UNIT PRICE	TOTAL																		
Expansion Board/ 212610	1	\$181.46	\$181.46																		
Tax		\$9.07	\$9.07																		
Shipping		\$30.00	\$30.00																		
TOTAL			\$220.53																		
Additional Labor Cost to Perform Repairs	<p>Labor: \$1,000.00</p> <p>HVAC Labor Tech/10 hours/Rate \$100.00 per hour = \$1,000.00</p>																				
Total Cost of Repair	\$1,220.53																				