

Additional Funding Request

Submitted: **07/05/2022**

MD066 Hand wash sink Leaks	CSS #1371 WO#18335											
Description of Repairs	S&S will remove and replace the spray head on the hand sink in the OMS work bay.											
Original SC Investigative Diagnosis	\$250.00											
Diagnosis: Initial Work Order	Repair water leaks on hand wash sink in OMS work bay.											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$520.94 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts/Shipping detailed in Quote</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: right; padding: 2px;">\$520.94</td> <td style="text-align: right; padding: 2px;">\$520.94</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts/Shipping detailed in Quote	1	\$520.94	\$520.94
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Parts/Shipping detailed in Quote	1	\$520.94	\$520.94									
Additional Labor Cost to Perform Repairs	Labor: \$600.00 16 hours each/Plumbing Rate \$100.00 per hour = \$600.00											
Total Cost of Repair	\$1,370.94											