

Additional Funding Request

Submitted: 2/11/2021

| MD066- Cooling Tower Basin Transformer | CSS #28869 WO# 13641 | | | | | | | | | | | |
|---|---|------------|----------|--|------|----------|------------|-------|---------------------|---|----------|----------|
| Description of Repairs | S&S was onsite and found the class two transformer in the heater control box was not working, proposes to remove and replace the transformer, S&S will then complete a full system check to ensure everything is running properly | | | | | | | | | | | |
| Original SC Investigative Diagnosis | \$400.00 | | | | | | | | | | | |
| Diagnosis: Initial Work Order | Cooling tower at MD066 and found the basin iced over. We need a corrective maintenance ticket created to check the basin heater. Asset #md066-197. | | | | | | | | | | | |
| Explanation of Additional Costs for Repairs | N/A | | | | | | | | | | | |
| Additional Material Cost to Perform Repairs | Materials: \$136.60 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Transformer/1007182</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$136.60</td> <td style="text-align: left; padding: 2px;">\$136.60</td> </tr> </tbody> </table> | | | | ITEM | QUANTITY | UNIT PRICE | TOTAL | Transformer/1007182 | 1 | \$136.60 | \$136.60 |
| ITEM | QUANTITY | UNIT PRICE | TOTAL | | | | | | | | | |
| Transformer/1007182 | 1 | \$136.60 | \$136.60 | | | | | | | | | |
| Additional Labor Cost to Perform Repairs | Labor: \$600.00 Plumber Labor Tech/6 hours/Rate \$100.00 per hour = \$600.00 | | | | | | | | | | | |
| Total Cost of Repair | \$1,136.60 | | | | | | | | | | | |