

## Additional Funding Request

Submitted: 03/12/21

<b>MD066-Louvers not open</b>	<b>CSS #29391 WO# 13859</b>							
Description of Repairs	S&S will need further funding to work with TMI to resolve communication issue on unit.							
Original SC Investigative Diagnosis	<b>\$450.00</b>							
Diagnosis: Initial Work Order	Location is in the storage/cage area of bldg.1. Back near the offices. Unit is running but louvers are not open. BLDG EMS has fan in alarm.							
Explanation of Additional Costs for Repairs	N/A							
Additional Material Cost to Perform Repairs	<b>Materials: NA</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL
ITEM	QUANTITY	UNIT PRICE	TOTAL					
Additional Labor Cost to Perform Repairs	<b>Labor: \$500.00</b> HVAC Labor Tech/5 hours/Rate \$100.00 per hour = \$500.00							
<b>Total Cost of Repair</b>	<b>\$950.00</b>							
<b>CM Credit</b>	<b>(250.00)</b>							
<b>Final Total</b>	<b>\$700.00</b>							