

Additional Funding Request

Submitted: **4/26/2021**

MD066-Arms Vault Alarm	CSS #30243 WO#14148								
Description of Repairs	Diagnostic and possible repair for alarm in Arms Room								
Original SC Investigative Diagnosis	\$720								
Diagnosis: Initial Work Order	The ARMS ROOM IDS Alarms has gone off, Fort McCoy has determined that the alarms were triggered by Zone 12, motions censor and Zone 4 power supply. Fort McCoy has disconnected the two sensors until repairs can be made. POC is SFC David Williams @ (817) 846-4096								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"> </td><td style="text-align: left; padding: 2px;"> </td><td style="text-align: left; padding: 2px;"> </td><td style="text-align: left; padding: 2px;"> </td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL				
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Additional Labor Cost to Perform Repairs									
Total Cost of Repair	\$720.00								