

Additional Funding Request

Submitted: 06/01/2021

MD066 – Main DOAS AHU	CSS # 30476 WO#14168								
Description of Repairs	S&S proposes to braise the suction and liquid lines on circuit #1. S&S will then add R-410a to the system and complete a full system check to ensure the system is now running properly.								
Original SC Investigative Diagnosis	NA								
Diagnosis: Initial Work Order	Main DOAS AHU in Mechanical -Compressor alarm on system -								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$324.99</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">See detail parts in quote</td> <td style="text-align: left; padding: 2px;"></td> <td style="text-align: left; padding: 2px;">\$ 324.99</td> <td style="text-align: left; padding: 2px;">\$324.99</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	See detail parts in quote		\$ 324.99	\$324.99
ITEM	QUANTITY	UNIT PRICE	TOTAL						
See detail parts in quote		\$ 324.99	\$324.99						
Additional Labor Cost to Perform Repairs	<p>Labor: \$1000.00 10 hours each/Rate \$100.00 per hour = \$1000.00</p>								
Total Cost of Repair	\$1,324.99								