

Additional Funding Request

Submitted: 10/05/2021

MD066 – Outside lighting	CSS # 32691 WO# 15113											
Description of Repairs	S&S will need to return with a lift to further diagnose. S&S will include ballast & wire on the quote in case it can be fixed while onsite.											
Original SC Investigative Diagnosis	\$400.00											
Diagnosis: Initial Work Order	Parking lot lights Asset 373 MEP Lot Parking lot lights Assets 353 & 371											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$1,444.90 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;">Parts, Lift, Shipping (See attached quote for detail)</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: right;">1,444.90</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts, Lift, Shipping (See attached quote for detail)	1	1	1,444.90
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Parts, Lift, Shipping (See attached quote for detail)	1	1	1,444.90									
Additional Labor Cost to Perform Repairs	Labor: \$1000.00 10 hours each/Electrical Rate \$100.00 per hour = \$1,000.00											
Total Cost of Repair CM CREDIT	\$2,844.90 (\$750.00)											
Final Total of Repair	\$2094.90											