

## Additional Funding Request

Submitted: 11/5/2021

<b>MD066-Gate Arm</b>	<b>CSS #33002 WO#15355</b>								
Description of Repairs	Bruce Oliver 11/01/2021 Work Note Walked job to get material list. Will pick up & return. 2 GUYS 11/03/2021 Work Note Replaced damaged wood on gate. Work complete.								
Original SC Investigative Diagnosis	<b>NA</b>								
Diagnosis: Initial Work Order	The armature gate leading into the OMS and MEP area has broken. From looking at the pictures provided by SFC Williams, it looks like the damage may be due to rot and weathering. I would recommend to replace the arm with an arm made of something to withstand the elements better. POC is SFC David Williams at 817-846-4096								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p><b>Materials: \$ 101.87</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;"><b>ITEM</b></th> <th style="text-align: left; padding: 2px;"><b>QUANTITY</b></th> <th style="text-align: left; padding: 2px;"><b>UNIT PRICE</b></th> <th style="text-align: left; padding: 2px;"><b>TOTAL</b></th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"><b>PARTS</b></td> <td style="text-align: left; padding: 2px;"><b>1</b></td> <td style="text-align: left; padding: 2px;"><b>\$101.87</b></td> <td style="text-align: left; padding: 2px;"><b>\$101.87</b></td> </tr> </tbody> </table>	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	<b>PARTS</b>	<b>1</b>	<b>\$101.87</b>	<b>\$101.87</b>
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>						
<b>PARTS</b>	<b>1</b>	<b>\$101.87</b>	<b>\$101.87</b>						
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$1,200.00</b>            15 hours each/Plumbing Rate \$80.00 per hour = \$1200.00</p>								
<b>Total Cost of Repair</b>	<b>\$1,301.87</b>								