

## **Additional Funding Request**

Submitted: 7/7/2022

<b>MD066- IDS Panel Door switch</b>	<b>CSS #34844 WO#16788</b>								
Description of Repairs	IDS panel Box switch repaired or replaced in the Arms Room Vault.								
Original SC Investigative Diagnosis	<b>\$120.00 (Service call)</b>								
Diagnosis: Initial Work Order	Need to replace the IDS panel door switch and board inside the box to clear all alarms.								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p><b>Materials: \$192.00</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">See parts in Quote</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$192.00</td> <td style="text-align: left; padding: 2px;">\$192.00</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	See parts in Quote	1	\$192.00	\$192.00
ITEM	QUANTITY	UNIT PRICE	TOTAL						
See parts in Quote	1	\$192.00	\$192.00						
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$840.00</b>            7 hours each/ Rate \$120.00 per hour = \$840.00</p>								
<b>Total Cost of Repair</b>	<b>\$1,152.00</b>								